



JON M. HUNTSMAN, JR.

Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program March 16, 2006

Supervisor LDZ

Mine Name: Millcreek 1-2-3

Operator Name: Mike Dettamanti - D. Wood

P.O. Box 291

Kanab, Utah 84741

Permit number: S/053/051

Inspection Date: February 27, 2006

Time: 6:15 PM

Inspector(s): Doug Jensen

Other Participants: None

Mine Status: Inactive

Weather: Sunny, Cool

Elements of Inspection

1. Permits, Revisions, Transfer, Bonds
2. Public Safety (shafts, adits, trash, signs, highwalls)
3. Protection of Drainages / Erosion Control
4. Deleterious Material
5. Roads (maintenance, surfacing, dust control, safety)
6. Concurrent Reclamation
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)
8. Water Impoundments
9. Soils
10. Revegetation
11. Air Quality
12. Other

Evaluated	Comment	Enforcement
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Inspected the site while I was in the area.

Inspection Summary:

There has been no activity at this site since my last inspection on 9/29/05. I GPS'd and took photos of the location of the site on my previous visit. Because there were no changes at the site, I did not repeat the process.

Conclusions and Recommendations:

I will continue to monitor the site when I am in the area.

Inspector's Signature

Doug Jensen

Date:

3/16/06

dj:pb

cc:

Mike Dettamanti

Steve Winslow, Forest Service, Beaver FO

O:\M053-Washington\S0530051-Millcreek123\Inspections\02272006insp.doc